

Type Herst.	DF 1 Mu, Te, Va
U_f I_f Heizart	1,4 0,05 B
Verw. Kbn-Lg. Kbn-Ø	H — —
U_a U_{g_0} U_{g_4} U_{g_3} U_{g_2} U_{g_1}	90 — — 0 90 0
I_a I_{g_2}	1,2 0,3
S D R_i	0,75 — 1500
R_k R_a R_{g_3}	— — —
$U_{g_1} \sim$ V $N_a \sim$	— 1200 —
U_b max U_{g_2} max N_a max N_{g_2} max R_{g_1} max	— — — — —
$c_{p/a}$	—



DF 1