


Type ähnlich	6 Ж 6 С = Z-62 D —
U_f I_f Heizart	6,3 0,5 \cong
Verw.	P
U_a U_{g_2} U_{g_1}	250 100 -2,4
I_a I_{g_3} S D	10 2,5 7,5 —
R_t R_a R_k	2000 $cg/a =$ $< 0,03$
$U_a \text{ max}$ $N_a \text{ max}$ $R_{g_1} \text{ max}$	$c/e = 9$ 2,5 $c/a = 6$
$N_a \sim$	$N_{g_2} = 0,5$



6 Ж 6 С